DPM 6064

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

SECTION I						10 M	
MANUFACTURER'S NAME			GENCY TELEP		o. 👸 🐧		
Turco Products, Inc.			(213)	634-330			
ADDRESS (Number, Street, City, State, and ZIP) 24600 South Main Street	<i>Code)</i> , Carson,	Ca 9074	9	•	6		
CHEMICAL NAME AND SYNONYMS			ape name an urco Air	1 SYNONYMS		WITTE STATE	
CHEMICAL FAMILY		FORMULA					
SFC	rion II - HAZA	ARDOUS INGREDIE	NTS				
HAZARDOUS M	IXTURES OF LIC	QUIDS, SOLIDS,	OR GASES				
		C.A.S. NUMBER	DOT SPILL CAT.		%	TLV UNITS	
Sodium silicate		6834- 92-0	Un- listed	Un- listed	21	10mg/MB	
		7601-	115000	Un-		Not	
Sdoium phosphate, tribas	1C	54-9	D	listed	13	establi	
Other components not de	fined as	hazardous	by US D	ept. of	Labor	r	
Carcinogens per OSHR, 5/3	3/73	•		•	None		
SE	CTION III -	PHYSICAL D	ATA				
BOILING POINT (°F.)	NA	SPECIFIC GRA	SPECIFIC GRAVITY (H2O=1)				
/APOR PRESSURE (mm Hg.)	NA	PERCENT, VO				NA	
/APOR DENSITY (AIR=1)	NA	EVAPORATION RATE				NA	
SOLUBILITY IN WATER	Complet						
APPEARANCE AND ODOR Off-whit	e granula	r mix					
SECTION IV	FIRE AND	EXPLOSION	HAZARD D	ATA			
LASH POINT (Method used) One		FLAMMABLE LIMITS NA Let					
xtinguishing media on-flammable							
PECIAL FIRE FIGHTING PROCEDURES							

PAGE/(1) Revise

Revised: 7/80 (C

Reviewed:6/82

Form OSHA-20 BOE-C6-0225262

DPM 6064

SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE: See Section II EFFECTS OF OVEREXPOSURE: Skin: Defatting, minor irritation. Eyes: Non-permanent irritation. Inhalation: Irritation, nausea. Ingestion: Gastric disturbances, nausea. EMERGENCY AND FIRST AID PROCEDURES: Skin: Wash with water. Remove contaminated clothing. Launder before reuse. Eyes: Flush with water or 1% boric acid. Obtain medical attention, if irritation persists. Inhalation: Remove to fresh air. Ingestion: Do not induce vomiting. If conscious, diluty giving large volumes of milk or water. Never attempt to give anything by mouth to an unconscious person. Obtain medical attention.	te 3

SECTION VI - REACTIVITY DATA	CTION VI -	SEC.			
ABLE CONDITIONS TO AVOID	CONDITIO	BLE	UNSTA	STABILITY UNS	
LE X		X	STAB		
ils to avoid)		to avoid)	BILITY (Materia	INCOMPATABIL	
ION PRODUCTS		N PRODUCTS	S DECUMPOSIT	HAZARDOUS DI	
MAY OCCUR CONDITIONS TO AVOID		AY OCCUR	MAY		
WILL NOT OCCUR X	UR X	WILL NOT OCCUR		POLYMERIZATION	
MAY OCCUR CONDITIONS TO AVOID	v	N PRODUCTS	S DECUMPOSIT	HAZARDOUS D	

SECTION VII - SPILL OR LEAK PROCEDURES
Steps to be taken in case material is released or spilled. Flush residual amount Sweep up and collect in sealable container. Flush residual amount
to sewer with water.
Neutralize and separate floatable grease and oil for incineration
or disposal in approved landfill. Release neutralized waters to
sewer in accordance with Federal, State, and local regulations.

	SECTION VIII - SPECIAL PR	OTECTIO	NIN	FORMATION
RESPIPATORY PRO Respirator	with mechanical filter f	or mist	or	dust conditions
VENTILATION	LOCAL EXHAUST X			
	MECHANICAL (General)	 .		OTHER
PROTECTIVE GLOV	/ES	EYE PROTEC	al	goggles
OTHER PROTECTIVE RUbber DOC	ve equipment ots and apron			

SECTION IX - SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store in closed containers away from excessive heat or direct	
sunlight.	
None	

dg PAGE (2) GPO 934-110

Form OSHA-20 Rev. May 72